



4. ADDED AS SECONDARY OPERATION.
1. Revised jacks to front panel.
  2. ALL DIODES ARE TYPE 1N4003, EXCEPT AS NOTED.
  3. ALL CAPACITORS IN MICORFARADS, EXCEPT AS NOTED.
  4. ALL RESISTORS IN OHMS

NOTES: UNLESS OTHERWISE SPECIFIED.

12340 World Trade Drive San Diego, CA 92128 (858) 487-1600 FAX 487-6629	
<b>CARVIN</b>	
<b>R600, R100</b> System Master	
DRAWN BY: GEORGE DREYER	DATE: 10JUNE97
APPROVED:	DATE:
PCB NO: 30-40600	REV: K
ASSY. NO: 80-40626	REV: M
NO: 80-41000	REV: M
REVISED BY: GEORGE DREYER	DATE: 14April 2000

- Changes from Assembly Rev (H3).
1. Revised jacks to front panel.
  2. Revised header numbering.
  3. Revised PCB to Rev (G).
- Changes from Assembly Rev (H4).
1. Moved Clip LEDs to Front PCB: D103, D203.
  2. Revised headers H3 & H14.
  3. Revised PCB to Rev (H).
- Changes from Assembly 80-41000 Rev (I).
1. R519 from 100Ω to 36Ω.
- Changes from Assembly 80-41000 and 80-40626 Rev (J&I).
1. C28 from .022u to .033u.
- Changes from Assembly 80-41000 and 80-40626 Rev (J1).
1. total change to new power amp, SMT and Speakers.
- Changes from PCB 3040626 Rev (J).
1. power amp protection changes.

- CHANGES FOR R1000 ASSEMBLY: 80-41000
1. Add Q110, Q210 (Type: MJL 21194).
  2. Add Q114, Q214 (Type: MJL 21193).
  3. Add R168-R175, R268-R275 (0.22Ω).
  4. Change C501, C502 to 10kMf @ 80V.

