



4. ADDED AS SECONDARY OPERATION.

- ALL DIODES ARE TYPE 1N4003, EXCEPT AS NOTED.
- ALL CAPACITORS IN MICROFARADS, EXCEPT AS NOTED.
- ALL RESISTORS IN OHMS

Changes from Assembly Rev (H3).

- 1. Revised jacks to front panel.
- 2. Revised header numbering.
- 3. Revised PCB to Rev (G).

Changes from Assembly Rev (H4).

- 1. Moved Clip LEDs to Front PCB: D103, D203.
- 2. Revised headers H3 & H14.
- 3. Revised PCB to Rev (H).

CHANGES FOR R1000 ASSEMBLY: 80-41000

- 1. Add Q109, Q209 (Type: MJL 21194).
- 2. Add Q112, Q212 (Type: MJL 21193).
- 3. Add R441, R442, R241, R242 (0.22Ω).
- 4. Change C501, C502 to 10Kmf @ 80V.
- 5. Change R217, R417 From 4.7K to 3.3K.

CARVIN		12340 World Trade Drive San Diego, CA 92128 (619) 487-1600 FAX 487-6629	
R600, R1000 System Master			
DRAWN BY:	DATE:		
GEORGE DREYER	10JUNE97		
APPROVED:	DATE:		
PCB NO: 30-40600	REV:		
ASSY. NO: 80-40626	REV: Pending(H3)		
NO: 80-41000	DATE:		
REVISED BY: C. MCEUEN	DATE: 21JUL98		

